

Collection


## **INDUSTRIA**

Article


# ID328\_23

Description

## Wall mounted bath spout







G1/2" male

Aerator Flow Rate (+/-10%)

M24x1 1 BAR 2 BAR 3 BAR 17.5 |\mathrm{1}{m} 23 |\mathrm{1}{m} 29 |\mathrm{1}{m}

Production

Main body is a single hot stamped pieces

Material

**BRASS** 

According to CuZn42 (CW510L) Max Lead content: 0.2%




T. +39 030 802101 F. +39 030 803097 info@weareib.it P.IVA 01785230986 capitale sociale €420.000,00 i.v. www.weareib.it







Parts list				
ITEMS	CODE	DESCRIPTION	FIN	QTÀ
1	AC0012377	Spout-out Ø26 L195	F	1
2	AQ0015036	Aerator Ø26 H17 M24x1 flow sraightener	F	1
		(40.9100.33301)		
3	AQ0009421	OR 26x2 NBR 70 SH	-	1
4	AC0018091-TI	Rosette Ø70 Ø26.5 H5 knurled	F	1





**७** f 𝒫



#### WARRANTY

All IB Rubinetterie SpA products are warrented for 10 years from the date of purchase, for the following cases:

- Defects of casting, porosity and chrome plating.
- Operating defects caused by incorrect fabrication.

The warranty provides for repair or replacement of products with fabrication defects recognized by our technical office. There is no other type of compensation anche the merchandise must be returned FOB our werehouse. The warranty only cover surface defects (scartches, dings, etc.) on fitting that have not been installed and used, returned in its original packaging with all components. O-ring, gasket seals and components subject to wear proportional to use are warranted for 2 years.

## The warranty is void in the following cases:

Error installing and putting the product into service.

Deterioration of finisched surfaces due to use of cleaning products containing acids or abrasive substances. Deterioration of surface with finishes other than chrome plating. Their durability is, in fact, dependent on the user's care and gentleness of use.

Deterioration of the fitting due incorrect installation.

Improper repairs and maintenance performed without the company's prior authorization.

The warranty from IB Rubinetterie SpA is not renewable.

### Cleaning

We recommanded cleaning the finish surfaces with water and soap, using a soft cloth. Do not use detergents that cointain hydrochloric acid or abrasive substances.





F f P