

Collection

BRERA Article

RR300


Description

Exposed parts for manual wall mixer

Built-in body to be purchased separately INC300







Cartridge Ø35 ceramic cartridge	Threaded fitting		
Aerator	Flow Rate (+/-10%) 1 BAR 11.5 I\m	2 BAR 16.3 l\m	3 BAR 20 I\m
Production	Material		

Main body is a machined from a solid pieces


BRASS According to CuZn39Pb3 (CW614N) Max Lead content: 2.5%



P.IVA 01785230986 capitale sociale €420.000,00 i.v. www.weareib.it



Parts list					
ITEMS	CODE	DESCRIPTION		QTÀ	
1	CPIN206CC-19	Mixer 47x47 x recessed	-	1	
1.1	AQ0015684	Gasket Ø31 H3.5 Ø7 Ø7.5	-	1	
1.2	AQ0015357	Grubscrew M3x10 flat point	-	1	
1.3	AS0013040	Insert 47x47 H11 M37x1.5	G	1	
1.4	AQ0004095	Ceramic cartridge Ø35 9x9 (K35A)	-	1	
1.5	AC0010445	Recessed ring Ø41 M37x1.5 H40.7	F	1	
1.6	AQ0001040	Cartridge ring nut M37x1.5 H9	G	1	
2	AQ0003630	Cartridge ring nut cover M37x1.5	F	1	
3	AQ0015829	Rubber packing double-sided tape 75x75x8x1	-	1	
4	AC0013100-TI	Plate 85X85 x2 300	F	1	
5	AC0017970	Handle Ø42 H40	F	1	
6	AQ0001082	Grubscrew M4x4 cone point	-	1	
7	AQ0006650	Plug cover Ø7	F	1	



IB RUBINETTERIE s.p.a via dei Pianotti 3/5 25068 Sarezzo (BS) - Italy - **T.** +39 030 802101 **F.** +39 030 803097 info@weareib.it **P.IVA** 01785230986 capitale sociale €420.000,00 i.v. www.weareib.it





WARRANTY

All IB Rubinetterie SpA products are warrented for 10 years from the date of purchase, for the following cases:

- Defects of casting, porosity and chrome plating.
- Operating defects caused by incorrect fabrication.

The warranty provides for repair or replacement of products with fabrication defects recognized by our technical office. There is no other type of compensation anche the merchandise must be returned FOB our werehouse. The warranty only cover surface defects (scartches, dings, etc.) on fitting that have not been installed and used, returned in its original packaging with all components. O-ring, gasket seals and components subject to wear proportional to use are warranted for 2 years.

The warranty is void in the following cases:

Error installing and putting the product into service.

Deterioration of finisched surfaces due to use of cleaning products containing acids or abrasive substances. Deterioration of surface with finishes other than chrome plating. Their durability is, in fact, dependent on the user's care and gentleness of use.

Deterioration of the fitting due incorrect installation.

Improper repairs and maintenance performed without the company's prior authorization.

The warranty from IB Rubinetterie SpA is not renewable.

Cleaning

We recommanded cleaning the finish surfaces with water and soap, using a soft cloth. Do not use detergents that cointain hydrochloric acid or abrasive substances.



P.IVA 01785230986 capitale sociale €420.000,00 i.v.

