


Collection

ELIO Article

E0317


Description


Wall mounted spout





Dimensions






Cartridge	Threaded fitting G1/2" male	-	
Aerator	Flow Rate (+/-10%)		
M16.5x1	1 BAR 35 l\m	2 BAR 45 l\m	3 BAR 55 l\m
Production	Material		
Main body is a single hot stamped pieces	BRASS According to CuZn42 (CW510L) Max Lead content: 0.2%		

P.IVA 01785230986 capitale sociale €420.000,00 i.v. www.weareib.it







Parts list				
ITEMS	CODE	DESCRIPTION	FIN QTÀ	
1	CPELCCX24V-19	Pout-out tube 24x24	F	1
1.1	AQ0014729	Aerator cachè M16.5x1 neostrahl (01.5175.000)	-	1
1.2	AC0016826	Spout 24X24 L243 90gr	F	1
1.3	AQ0010857	OR 12.5x2 NBR 70 SH	-	1
1.4	AS0011681	Insert M16x1 G1/2" L23	G	1
2	AC0016875	Flat 85x85x2 foro 24x24	F	1
3	AQ0015829	Rubber packing double-sided tape 75x75x8x1	-	1

IB RUBINETTERIE s.p.a via dei Pianotti 3/5 25068 Sarezzo (BS) - Italy - **T.** +39 030 802101 **F.** +39 030 803097 info@weareib.it **P.IVA** 01785230986 capitale sociale €420.000,00 i.v. www.weareib.it





WARRANTY

All IB Rubinetterie SpA products are warrented for 10 years from the date of purchase, for the following cases:

- Defects of casting, porosity and chrome plating.
- Operating defects caused by incorrect fabrication.

The warranty provides for repair or replacement of products with fabrication defects recognized by our technical office. There is no other type of compensation anche the merchandise must be returned FOB our werehouse. The warranty only cover surface defects (scartches, dings, etc.) on fitting that have not been installed and used, returned in its original packaging with all components. O-ring, gasket seals and components subject to wear proportional to use are warranted for 2 years.

The warranty is void in the following cases:

Error installing and putting the product into service.

Deterioration of finisched surfaces due to use of cleaning products containing acids or abrasive substances. Deterioration of surface with finishes other than chrome plating. Their durability is, in fact, dependent on the user's care and gentleness of use.

Deterioration of the fitting due incorrect installation.

Improper repairs and maintenance performed without the company's prior authorization.

The warranty from IB Rubinetterie SpA is not renewable.

Cleaning

We recommanded cleaning the finish surfaces with water and soap, using a soft cloth. Do not use detergents that cointain hydrochloric acid or abrasive substances.



P.IVA 01785230986 capitale sociale €420.000,00 i.v.

