

Collection


SOLFERINO

Article

S0003


Description

Wall mounted toothbrush holder





| Parts list | | | | |
|------------|--------------|---------------------------------|-----|-----|
| ITEMS | CODE | DESCRIPTION | FIN | QTÀ |
| 1 | AQ0015654_8 | External tube Ø50 | F | 1 |
| 2 | AQ0015654_7A | Tank Ø45 H95 | - | 1 |
| 3 | AC0017709 | Cap Ø55 H10 | F | 1 |
| 4 | AQ0015654_12 | Screw M5x8 TSP cros UNI 7688 | - | 1 |
| 5 | AQ0015654_10 | Wall plug | F | 1 |
| 6 | AQ0015654_13 | Grubscrew M5x6 cone point | - | 1 |
| 7 | AQ0015654_14 | Washer Ø10 Ø5.3 UNI8842-A | - | 1 |
| 8 | AQ0015654_15 | M5 UNI 5588 stainless steel nut | - | 1 |
| 9 | AQ0015654_16 | Inox screw Ø4 L50 | - | 2 |
| 10 | AQ0015654_17 | Wall plate | - | 1 |
| 11 | AQ0015654_18 | Dowel fisher Ø8 L40 | - | 2 |



IB RUBINETTERIE s.p.a via dei Pianotti 3/5 25068 Sarezzo (BS) - Italy - **T.** +39 030 802101 **F.** +39 030 803097 info@weareib.it **P.IVA** 01785230986 capitale sociale €420.000,00 i.v.

www.weareib.it





WARRANTY

All IB Rubinetterie SpA products are warrented for 10 years from the date of purchase, for the following cases:

- Defects of casting, porosity and chrome plating.
- Operating defects caused by incorrect fabrication.

The warranty provides for repair or replacement of products with fabrication defects recognized by our technical office. There is no other type of compensation anche the merchandise must be returned FOB our werehouse. The warranty only cover surface defects (scartches, dings, etc.) on fitting that have not been installed and used, returned in its original packaging with all components. O-ring, gasket seals and components subject to wear proportional to use are warranted for 2 years.

The warranty is void in the following cases:

Error installing and putting the product into service.

Deterioration of finisched surfaces due to use of cleaning products containing acids or abrasive substances. Deterioration of surface with finishes other than chrome plating. Their durability is, in fact, dependent on the user's care and gentleness of use.

Deterioration of the fitting due incorrect installation.

Improper repairs and maintenance performed without the company's prior authorization.

The warranty from IB Rubinetterie SpA is not renewable.

Cleaning

We recommanded cleaning the finish surfaces with water and soap, using a soft cloth. Do not use detergents that cointain hydrochloric acid or abrasive substances.



www.weareib.it

D f P

P.IVA 01785230986 capitale sociale €420.000,00 i.v.