

Collection

AQUARIVA


Article


AV520

Description

Semi-built in showerhead with rain







Cartridge -	Threaded fitting G1/2" M			
Aerator	Flow Rate (+/-10%)			
-	1 BAR 10 l\m	2 BAR 12.5 l\m	3 BAR 15 l\m	

Production

Main body is a single casted pieces

Material


BRASS

According to CuZn35Pb2AI-B (CB752S)


Max Lead content: 1.36%







Parts list			
ITEMS	CODE	DESCRIPTION	QTÀ
1	AQ0017898	Shower head 350x530 rain	1
1.1	AQ0017898 1	350x530 rain shower head	1
1.2	AQ0017898 2	Screw M4x10 TB with flange Ø9.3	4
1.3	AQ0017898 3	3 modules gasket	5
1.4	AQ0017898 4	Shower head supply connection	5
1.5	AQ0017898 5	NEW closing plate 285x465	1
1.6	AQ0017898 6	Washer for M4 screws DIN 6798 A	24
1.7	AQ0017898_7	M4x8 TCEI UNI 5931 screw	23
1.8	AQ0017898_8	O-Ring 18x2	5
1.9	AQ0017898_9	Shower head connection	5
1.10	AQ0017898_10	Connection art.801 G1 / 2 "M Ø10	1
1.11	AQ0017898_11	RILSAN PA12 J7 Ø10 Ø8 pipe	1
1.12	AQ0017898_12	Rotating elbow RL31 G3/8"M Ø10	2
1.13	AQ0017898_13	Double turn attack. RL32 G3/8"M Ø10	3
1.14	AQ0017898_14	Fox RL5 intermediate T fitting Ø10	1
1.15	AQ0017898_15	Shower head fixing profile with rivets	2
1.16	AQ0017898_16	Screw SPEI M6x40 UNI5933	4
1.17	AQ0017898_17	Bracket with rivets for fixing the shower head	1







WARRANTY

All IB Rubinetterie SpA products are warrented for 10 years from the date of purchase, for the following cases:

- Defects of casting, porosity and chrome plating.
- Operating defects caused by incorrect fabrication.

The warranty provides for repair or replacement of products with fabrication defects recognized by our technical office. There is no other type of compensation anche the merchandise must be returned FOB our werehouse. The warranty only cover surface defects (scartches, dings, etc.) on fitting that have not been installed and used, returned in its original packaging with all components. O-ring, gasket seals and components subject to wear proportional to use are warranted for 2 years.

The warranty is void in the following cases:

Error installing and putting the product into service.

Deterioration of finisched surfaces due to use of cleaning products containing acids or abrasive substances. Deterioration of surface with finishes other than chrome plating. Their durability is, in fact, dependent on the user's care and gentleness of use.

Deterioration of the fitting due incorrect installation.

Improper repairs and maintenance performed without the company's prior authorization.

The warranty from IB Rubinetterie SpA is not renewable.

Cleaning

We recommanded cleaning the finish surfaces with water and soap, using a soft cloth. Do not use detergents that cointain hydrochloric acid or abrasive substances.



□ f P