

Collection

BELMONDO

Article

BL400

Description


Two holes wall mounted shower








Dimensions








Ceramic headwork G1/2" ceramic headwork	Threaded fitting G1/2" female				
Aerator	Flow Rate (+/-109 1 BAR 28 l\min	‰) 2 BAR 40 I∖min	3 BAR 49.3 l\min		
Production Main body is a single casted pieces	Material BRASS According to Max Lead col				

P.IVA 01785230986 capitale sociale €420.000,00 i.v. www.ibrubinetti.it





Parts list					
ITEMS	CODE	DESCRIPTION		QTÀ	
1	CC0002160	Lever	F	2	
2	AQ0010153	OR 10x2 NBR 70 SH	-	2	
3	CC0002162	Octagonal bell H70	F	2	
4	AQ0010274	Rubber packing Ø38x33.5x2	-	2	
5	AQ0010617	Click connection for headworks	-	2	
6	AQ0010529	Ceramic headwork 90° SX H38.5 8x20	-	1	
7	AQ0010528	Ceramic headwork 90° DX H38.5 8x20	-	1	
8	CT0002005	Built-in stopcocks G1/2"	G	2	



IB RUBINETTERIE s.p.a via dei Pianotti 3/5 25068 Sarezzo (BS) - Italy - **T.** +39 030 802101 **F.** +39 030 803097 info@ibrubinetterie.it

P.IVA 01785230986 capitale sociale €420.000,00 i.v. www.ibrubinetti.it





WARRANTY

All IB Rubinetterie SpA products are warrented for 10 years from the date of purchase, for the following cases:

- Defects of casting, porosity and chrome plating.
- Operating defects caused by incorrect fabrication.

The warranty provides for repair or replacement of products with fabrication defects recognized by our technical office. There is no other type of compensation anche the merchandise must be returned FOB our werehouse. The warranty only cover surface defects (scartches, dings, etc.) on fitting that have not been installed and used, returned in its original packaging with all components. O-ring, gasket seals and components subject to wear proportional to use are warranted for 2 years.

The warranty is void in the following cases:

Error installing and putting the product into service.

Deterioration of finisched surfaces due to use of cleaning products containing acids or abrasive substances. Deterioration of surface with finishes other than chrome plating. Their durability is, in fact, dependent on the user's care and gentleness of use.

Deterioration of the fitting due incorrect installation.

Improper repairs and maintenance performed without the company's prior authorization.

The warranty from IB Rubinetterie SpA is not renewable.

Cleaning

We recommanded cleaning the finish surfaces with water and soap, using a soft cloth. Do not use detergents that cointain hydrochloric acid or abrasive substances.

P.IVA 01785230986 capitale sociale €420.000,00 i.v. www.ibrubinetti.it

