

Collection

BELMONDO

Article

BT327


Description

Tub filler Wall spout





Dimensions



Ceramic headwork G1/2" ceramic headwork	Threaded fitting G1/2" male			
Aerator	Flow Rate (+/-10%)			
M16.5x1	1 BAR 12 I\min	2 BAR 17 I∖min	3 BAR 22 l\min	
Production	Material			
Main body is a single casted pieces	BRASS			

According to CuZn35Pb2AL-B (CB752S) Max Lead content: 1.36%




IB RUBINETTERIE s.p.a via dei Pianotti 3/5 25068 Sarezzo (BS) - Italy - P.IVA 01785230986 capitale sociale . €420.000,00 i.v.

www.weareib.it 🖸 f 🖓



Parts list				
ITEMS	CODE	DESCRIPTION		QTÀ
1	CC0001938	Spout for recessed basin mixer L197		1
2	AQ0014729	Aerator cachè M16.5x1 neostrahl (01.5175.000)		1
3	AQ0010117	Grubscrew M5x4 cone point		1
4	AQ0004630	OR 17.16x1.78 NBR 70 SH	-	2
5	AS0010502	Insert Ø25.8 G1/2" L36.5	G	1
6	AQ0006637	OR 21.95x1.78 NBR 70 SH	-	2
7	AS0010503	Insert Ø31.5 H41	G	1



REAL PROVIDE CONTROL OF

T. +39 030 802101 **F.** +39 030 803097 info@weareib.it **P.IVA** 01785230986 capitale sociale €420.000,00 i.v.

www.weareib.it

f P



WARRANTY

All IB Rubinetterie SpA products are warrented for 10 years from the date of purchase, for the following cases:

- Defects of casting, porosity and chrome plating.
- Operating defects caused by incorrect fabrication.

The warranty provides for repair or replacement of products with fabrication defects recognized by our technical office. There is no other type of compensation anche the merchandise must be returned FOB our werehouse. The warranty only cover surface defects (scartches, dings, etc.) on fitting that have not been installed and used, returned in its original packaging with all components. O-ring, gasket seals and components subject to wear proportional to use are warranted for 2 years.

The warranty is void in the following cases:

Error installing and putting the product into service.

Deterioration of finisched surfaces due to use of cleaning products containing acids or abrasive substances. Deterioration of surface with finishes other than chrome plating. Their durability is, in fact, dependent on the user's care and gentleness of use.

Deterioration of the fitting due incorrect installation.

Improper repairs and maintenance performed without the company's prior authorization.

The warranty from IB Rubinetterie SpA is not renewable.

Cleaning

We recommanded cleaning the finish surfaces with water and soap, using a soft cloth. Do not use detergents that cointain hydrochloric acid or abrasive substances.



www.weareib.it

D f P

P.IVA 01785230986 capitale sociale €420.000,00 i.v.