

Collection


# MARMO

Article


## MR320\_2

Description

Wall mounted spout







Cartridge	Treaded fitting Treaded fitting G1/2" male Flow Rate (+/-10%)		
Aerator			
M24x1	1 BAR 6.5 l\min	2 BAR 8 I\min	3 BAR 8 I\min
Production	Material		
Main body is a machined from a solid pieces	BRASS		


BRASS According to CuZn39Pb3 (CB614N) Max Lead content: 2.5%



**P.IVA** 01785230986 capitale sociale €420.000,00 i.v. www.weareib.it



ELENCO PARTI				
ELEMENTO	CODICE	DESCRIZIONE	QTÀ	
1	AQ0015103	OR 26x1 NBR 70 SH	1	
2	AC0012591	Anello Ø30 Ø26.9 H2	1	
3	AC0012558	Bocca Ø26 L145	1	
4	AQ0014681	Aeratore Ø26 H17 M24x1 (40.1053.33300)	1	
5	AQ0014950	Copertura marmo Ø68 H40 nero marquinia	1	
6	AQ0015558	Vite Ø7.1 M6 H9 grigio scuro	1	
7	AQ0001450	OR 47.37x1.78 NBR 70 SH	2	
8	AS0012527	Anello bocca Ø52.4 H34 Ø26.5	1	
9	AQ0006586	OR 25.12x1.78 NBR 70 SH	2	
10	AQ0009591	Guarnizione Ø40 Ø49.5 H1.5	1	



**IB RUBINETTERIE** s.p.a via dei Pianotti 3/5 25068 Sarezzo (BS) - Italy - **T.** +39 030 802101 **F.** +39 030 803097 info@weareib.it **P.IVA** 01785230986 capitale sociale €420.000,00 i.v.

www.weareib.it





### WARRANTY

All IB Rubinetterie SpA products are warrented for 10 years from the date of purchase, for the following cases:

- Defects of casting, porosity and chrome plating.
- Operating defects caused by incorrect fabrication.

The warranty provides for repair or replacement of products with fabrication defects recognized by our technical office. There is no other type of compensation anche the merchandise must be returned FOB our werehouse. The warranty only cover surface defects (scartches, dings, etc.) on fitting that have not been installed and used, returned in its original packaging with all components. O-ring, gasket seals and components subject to wear proportional to use are warranted for 2 years.

#### The warranty is void in the following cases:

Error installing and putting the product into service.

Deterioration of finisched surfaces due to use of cleaning products containing acids or abrasive substances. Deterioration of surface with finishes other than chrome plating. Their durability is, in fact, dependent on the user's care and gentleness of use.

Deterioration of the fitting due incorrect installation.

Improper repairs and maintenance performed without the company's prior authorization.

The warranty from IB Rubinetterie SpA is not renewable.

#### Cleaning

We recommanded cleaning the finish surfaces with water and soap, using a soft cloth. Do not use detergents that cointain hydrochloric acid or abrasive substances.



www.weareib.it

D f P

**P.IVA** 01785230986 capitale sociale €420.000,00 i.v.